



Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program January 21, 2009

Reviewed:

Mine Name: Pioneer Mine

Operator Name: Oilsand Technology Industry, Utah
Inspection Date: November 18, 2009
Inspector(s): L Heppler
Other Participants: none

Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcemen
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)			
8. Soils	$\overline{\square}$	$\overline{\boxtimes}$	
9. Revegetation			

Bond Amount: \$28,000 Permit fee is up to date

Purpose of Inspection: Routine annual Inspection. This site has not been inspected as a small mine site.

Inspection Summary: There is no disturbance at this site. When construction begins every effort should be made to salvage top soil from the site prior to mining.

Photos were taken to document site conditions.

Conclusions and Recommendations: OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:vs

cc: Andrew Kim

SITLA -Wstokes@utah.gov Jblake@utah.gov

O:\M047-Uintah\S0470091-PioneerMine\inspections\Insp-11182009.doc

DNR
OIL, GAS & MINING

